

Official Survey Record

THAYER

COUNTY, NEBRASKA

Page 10 of 12

Field Notes:

North 1/4 Corner Section 34-T1N-R2W

Found Aluminum Cap on a 5/8" X 3" Rebar at surface of Asphalt. Found 1/2" X 18" Rebar 9" deep. Aluminum Cap was set over a 1/2" Rebar. Lowered 1/2" Rebar to 30" and set Aluminum Cap on 5/8" Rebar over. Set Magnet on Aluminum Cap. After construction, set 5/8" X 24" Rebar to grade at surface of Asphalt with Aluminum Cap marked

THAYER COUNTY 2002

GC

T1N R2W

$\frac{1}{4}$ S 27
S 34

SECTION CORNER

with temporary ties as follows.

N 74.41' to nail and shiner top of corner fence post
NW 83.74' to nail and shiner top of fence post (3rd West of corner fence post)
SE 93.46' to nail and shiner NE side fence post
SSE 77.04' to nail and shiner West side power pole
N 4 ' to centerline Highway 8

NE Corner Section 34-T1N-R2W

Found Aluminum Cap on a 5/8" X 3" Rebar at surface over a 1/2" X 18" Rebar 6" deep over Magnet. Reset 1/2" Rebar to 31" deep and set Magnet on top. Set 5/8" Rebar with Aluminum Cap over Magnet 25" deep. After construction, set 5/8" X 24" Rebar to grade at surface of Asphalt with Aluminum Cap marked

THAYER COUNTY 2002

GC

T1N R2W

S27 + S26
S34 + S35

SECTION CORNER

with temporary ties as follows.

S 105.80' to nail and shiner West side East gate post
SSE 111.03' to nail and shiner NE side corner fence post
WNW 99.09' to nail and shiner SW side fence post
NNW 67.57' to nail and shiner East side corner fence post
S 24 ' to centerline Highway 8

North 1/4 Corner Section 35-T1N-R2W

Found Iron Pipe with NDOR Brass Cap 8" deep recorded as over Magnet. After construction found Iron Pipe and NDOR Brass Cap 8" deep. Temporary ties are as follows.

S 144.78' to nail and shiner West side power pole
NNE 64.58' to nail and shiner SE side telephone underground post
N 76.08' to nail and shiner top of corner fence post
NW 114.76' to nail and shiner top of fence post (7th West of corner fence post)
S 45 ' to centerline Highway 8