

Official Survey Record

THAYER COUNTY, NEBRASKA Page 8 of 12

Field Notes:

North 1/4 Corner Section 32-T1N-R2W

Found Aluminum Cap at surface of Asphalt on a 5/8" X 3" Rebar. Found 1/2" X 18" Rebar 8" deep. Lowered both to 24" and set Magnet on 1/2" Rebar. Cap is 0.15' East and 0.05' North of 1/2" Rebar. After construction, set 5/8" X 24" Rebar to grade at surface of Asphalt with Aluminum Cap marked

THAYER COUNTY 2002

GC

T1N R2W

1 S 29
4 S 32

SECTION CORNER

with temporary ties to 1/2" Rebar as follows.

S 94.19' to nail and shiner East side post
SE 122.76' to nail and shiner SW side power pole
N 76.69' to nail and shiner East side corner fence post
NE 101.46' to nail and shiner SE side fence post (4th East of gate post)
NW 85.33' to nail and shiner SW side fence post (3rd West of corner fence post)
S 8 ' to centerline Highway 8

NE Corner Section 32-T1N-R2W

Found Aluminum Cap at surface of Asphalt on a 5/8" X 3" Rebar. Found 1/2" X 18" Rebar 8" deep. Aluminum Cap is 0.50' East and 0.10' North of 1/2" Rebar. Lowered Cap and 1/2" Rebar to 24" and set Magnet on 1/2" Rebar. After construction, set 5/8" X 24" Rebar to grade at surface of Asphalt with Aluminum Cap marked

THAYER COUNTY 2002

GC

T1N R2W

S29 S28
S32 S33

SECTION CORNER

with temporary ties to 1/2" Rebar as follows.

NNW 93.99' to nail and shiner top of telephone underground post
SW 197.73' to nail and shiner SE side power pole
SSW 124.41' to top NE corner concrete right of way marker
S 117.16' to 5/8" X 24" rebar with tag "RM WW02" under power pole line East-West 3' East of centerline North-South road
N 88.10' to 5/8" X 24" rebar with tag "RM WW02" in line with telephone underground post on centerline North-South road
S 5 ' to centerline Highway 8
Bars North and South on line through corner