


BENCHMARK \*  
Chalkmalls in Power Pole  
Elevation = 100.00

BENCHMARK \*  
First Floor of This Building  
Elevation = 100.00 (Assumed)



LEGEND  
 ● - Monument Found  
 ○ - Set Standard Hole  
 R - Recorded Distance  
 M - Measured Distance

FIELD NOTES

At "A", "C", and "D" found chisled 'x' in concrete as recorded on survey by Richard C. Johnson, L.S. #429, dated 10/04/95  
 At "B" found iron pin in concrete as recorded on survey by Richard C. Johnson, L.S. #429, dated 10/04/95  
 At "E" set point on line "A" - "B" as shown  
 At "F" set point on line "C" - "D" as shown


LEGAL DESCRIPTION

Lot 8, Block 16 of the Original Plat of Beemer  
 Cuming County, Nebraska

SURVEYOR'S CERTIFICATE

I, Brian D. Benck, a registered surveyor of the State of Nebraska, hereby certify that this survey was made under my direction on June 2, 2000; that all dimensions are in feet and are correct to the best of my knowledge and belief.

*Brian D. Benck*  
 Brian D. Benck, Nebraska L.S. #536  
 GILMORE & ASSOCIATES, INC.  
 Survey #S-7061



\* Benchmark Disclaimer

A minimum of two benchmarks have been provided for the sole use of client and are not intended or represented to be suitable for use by any third party. The elevations established as benchmarks are vulnerable to change from the date such elevations were established due to a variety of reasons including, but not limited to, alteration of the physical structure the benchmarks are established upon, vandalism, swelling or subsidence of supporting soils, physical tampering, and construction or vehicular traffic on or adjacent to the benchmark. Gilmore & Associates, Inc., assumes no liability or responsibility for damages by client or any third party resulting from the misinterpretation, misidentification, or alteration of the benchmark elevations provided herein. Before utilizing any benchmark elevation noted herein, at all times the benchmark elevations must be verified and compared with each other as well as with elevations established for other permanent or semi-permanent structures noted, if any, to determine if any misinterpretation, misidentification, or alteration of the benchmark elevations has occurred. The standard of care utilized for professional surveying services in establishment of benchmark elevations is the care and skill ordinarily used by members of the surveyor's profession under similar circumstances at the same time and in the same locality.

REVISIONS

Phone (402) 564-2807  
 Fax (402) 564-2800  
 Box 555 2670 33rd Ave  
 Columbus, Nebraska 68602-0555

**GILMORE & ASSOCIATES INC.**  
 Engineers Architects Surveyors

Lot 8, Block 16  
 Original Plat of Beemer,  
 Cuming County, Nebraska  
 Legal Survey

DRN BY D.L.M.  
 DATE 06/28/2000  
 SCALE 1" = 10'  
 PROJ S-7061  
 F.B.  
 SHEET  
**1 of 1**