

Official Survey Record

-- GAGE -- COUNTY, NEBRASKA Page 2 of 3

Field Notes:

East 1/4 Corner Section 28-T6N-R8E

Found Aluminum Cap at surface of Asphalt. Temporary ties are as follows.

E 35.30' to top center of vinyl fence post (4th North of cemetery drive)
SE 30.61' to concrete nail top North end 24" corrugated metal pipe
SSE 54.09' to concrete nail top South end 24" corrugated metal pipe
SW 56.70' to concrete nail top South end 18" corrugated metal pipe
On centerline North-South road

NE Corner SE 1/4 NW 1/4 Section 27-T6N-R8E

Found Aluminum Cap 6" deep recorded as on a 1/2" X 30" Rebar. Temporary ties are as follows.

W 40.00' to 5/8" rebar on East-West road in line with chain link fence North
SSW 27.72' to nail and shiner West side power pole
NNW 35.82' to nail and shiner East side power pole
NW 56.05' to punch mark SW side chain link corner fence post at SW corner water treatment plant 1' above ground
SW 38.11' to nail and shiner top West end 18" corrugated metal pipe
N 3 ' to centerline East-West road
W 20 ' to centerline street South

Rebar near Center Section 27-T6N-R8E

Found 5/8" Rebar 1" below surface of Asphalt. Temporary ties are as follows.

NNE 79.87' to concrete nail at SW corner sidewalk to church where sidewalk meets curb and gutter
NNE 33.63' to nail and shiner West side power pole with three transformers
SE 21.95' to nail and shiner SW side power pole with street light
ESE 56.73' to nail and shiner SW side power pole in alley
W 24.0 ' to PK nail in joint between back of curb and edge walk
S 10.2 ' to center manhole cover
S 24.0 ' to back of curb

28-037E