

This plat was prepared at the request of Mr. Scott Kaup, Stuart, Nebraska.

FIELD NOTES

At "A" and "B", set drill holes in concrete. At "C" and "D", set 5/8" x 30" iron bars with plastic survey caps, as per owner's request. At "E", found 3/4" iron pipe as recorded by Donald L. Pettigrew, L.S. #305, plat of survey dated October 10, 2001. At "F", found 1" iron pipe. At "G", found 5/8" rebar with cap as recorded by Donald L. Pettigrew, L.S. #305, plat of survey dated October 10, 2001. At "H", found bent rebar. Replaced with 5/8" iron bar with plastic survey cap. At "I", found "X" in concrete as recorded by Donald L. Pettigrew, L.S. #305, plat of survey dated May 8, 1991. At "J" and "K", found 3/4" rebar as recorded by Donald L. Pettigrew, L.S. #305, plat of survey dated May 8, 1991. At "L", found 1" iron pipe as recorded by Robert D. Wortman, L.S. #408, plat of survey dated August 26, 1983. At "M", found 1" iron rod as recorded by Donald L. Pettigrew, L.S. #305, plat of survey dated May 8, 1991. At "N", found 2" iron pipe as recorded by Robert D. Wortman, L.S. #408, plat of survey dated August 26, 1983. At "O", computed temporary point. At "P", found nail. Said nail to be off-line 0.94 feet between "E" and "G", and measured 101.92 feet from point "G"; did not accept.

DESCRIPTION

Lots 10, 11, and the north 2 feet of Lot 12, Block 6, Hallock's Addition to the Village of Stuart, Holt County, Nebraska.

SURVEYOR'S CERTIFICATE

I, Clyde R. Flowers, Jr., a registered surveyor of the State of Nebraska, hereby certify that this survey was made under my direction on September 21, 2007; that all dimensions are in feet and are correct to the best of my knowledge and belief.



Clyde R. Flowers, Jr.
Clyde R. Flowers, Jr., Nebraska L.S. #357
GILMORE & ASSOCIATES, INC.